


Looking North. Intersection of Runway 35 and Taxiway B.



Looking North. Approach end of Runway 31 and Runway 35 at intersection of Taxiway A. Note that the hold marking for Runway 31 is north of the hold marking for Runway 35 on Taxiway Alpha.

Airport Authority: (816) 271-4886  
 Air Traffic Control: (816) 236-3682  
 Hours of Operation: 24 hours  
 Tower 0800 – 1800 (L)  
 Latitude: N39° 46.32'  
 Longitude: W94° 54.58  
 Elevation: 826 ft.  
 Variation: 4°E  
 From City: 3 miles NW  
 Sectional Chart: Kansas City  
 Control Tower: Yes  
 ARTCC: Kansas City 127.9  
 FSS: Columbia  
 NOTAMs Facility: COU AFSS  
 Wind Indicator: Yes  
 Beacon: Yes  
 Fire and Rescue: On site  
 Airline Operations: No  
 Customs: No  
 UNICOM: 122.95  
 CTAF 126.9  
 ATIS: 125.05  
 Ground: 121.9  
 Tower: 126.9  
 Clearance Delivery: ---  
 Approach Control Kansas City  
 APP/DEP 124.7  
 ASOS (816) 233-0666  
 VOR 115.5  
 RCO ---  
 Emergency ---



# AIRPORT RUNWAY SAFETY INFORMATION


## St. Joseph/ Rosecrans Memorial Airport

### (STJ)

### October 2002

RUNWAY SAFETY  
 Everyone's Responsibility  
 STAY ALERT!

FEDERAL AVIATION ADMINISTRATION  
 Central Region Runway Safety Program  
<http://www.faa.gov/runwaysafety>



# HIGH ALERT INTERSECTIONS

1. Pilots of light aircraft should exercise caution on Taxiway Bravo east of Runway 17/35. Other light aircraft may not be visible at the approach end of Runway 17 from Taxiway Bravo.
2. Pilots should exercise caution when approaching the complex intersection of Taxiway A, Runway 35 and Runway 31. Note that the hold marking for Runway 31 is north of the hold marking for Runway 35 on Taxiway Alpha.

